




Timber frame construction | Exterior wall











Timber frame construction | Dividing wall














Timber frame construction | Floor joint | Partial balloon framing Var. 1












Timber frame construction | Floor joint | Partial balloon framing Var. 2












Timber frame construction | Floor joint | Cross-laminated timber ceiling/floor












Timber frame construction | Floor joint | Continuous, 'recessed' DASAPLANO 0,01 membrane












Timber frame construction | Element joint | Exterior corner | Var. 1











Timber frame construction | Element joint | Exterior corner | Var. 2











Timber frame construction | Element joint | Interior corner | Var. 1











Timber frame construction | Element joint | Interior corner | Var. 2

Airtight sealing of racking boards with pro clima TESCON VANA (adhesion onto building structure).







Timber frame construction | Element joint | Interior corner | Var. 2 with adjacent interior wall

Airtight sealing of racking boards with pro clima TESCON VANA (adhesion onto building structure).

